

EPA Official Record

Notes ID: AC9D228106335E0E0549624B6CA43C2E

From: "Page, Elizabeth" <Elizabeth.Page@kochind.com>

To: Brandon Perkins/R10/USEPA/US@EPA

Copy To: "Knowles, Daren" <Daren.Knowles@fhr.com>

Delivered Date: 12/28/2010 11:12 AM PST

Subject: RE: Requested Reports - Flint Hills Resources Alaska

Brandon ,

Enclosed is information on your question regarding the schedule for the investigation of the laboratory sump system:

On December 15, 2010, we met with Brian Jackson of ADEC at the lab to discuss our proposed sampling locations. He indicated general agreement and asked that we prepare a sampling work plan.

On January 10, 2011, our implementation contractor will visit the lab to obtain site-specific information necessary to write the sampling work plan and plan the safe collection of the samples.

We expect to have a sampling work plan ready for submittal to ADEC by early February.

If the sampling work plan works through the review and approval process fairly quickly, we can expect to be in the field by late February.

You also asked about the specific location of the lab within the refinery. Please reference Figure 3 of the September 2010 Site Characterization Work Plan. The lab is the building located on the Northeast corner of Tank Farm Road and Process Avenue .

If you have any other questions, please let me know.

Thanks,

Liz

PLEASE NOTE:

New Street Address and Phone Number Below

Elizabeth Page, P.G.
Reiss Remediation, LLC
602 Strada Circle, Suite 121
Mansfield, TX 76063
Direct: (817) 842-9070
Fax: (817) 842-9110
Cell: (817) 723-4616

-----Original Message-----

From: Perkins.Brandon@epamail.epa.gov [<mailto:Perkins.Brandon@epamail.epa.gov>]
Sent: Monday, December 27, 2010 5:54 PM
To: Page, Elizabeth
Cc: Knowles, Daren
Subject: Re: Requested Reports - Flint Hills Resources Alaska

Hi Elizabeth

Thank you for sending these documents to me. Do you have an idea of when the additional investigation of the the lab drains will be conducted and complete? I'm also trying to determine where on the facility the laboratory is located. Is there a map or figure with its location?

Brandon Perkins, Site Assessment Manager Office of Environmental Cleanup U.S. Environmental Protection Agency, Region 10
206-553-6396

From: "Page, Elizabeth" <Elizabeth.Page@kochind.com>
To: Brandon Perkins/R10/USEPA/US@EPA
Cc: "Knowles, Daren" <Daren.Knowles@fhr.com>
Date: 12/21/2010 03:12 PM
Subject: Requested Reports - Flint Hills Resources Alaska

Brandon,

During the TPT meeting on December 14, 2010, you requested copies of the attached reports related to investigations performed around the FHRA laboratory in North Pole, AK.

Lab Sump Piping Failure Investigation Report, dated July 21, 2010
(CO-092_10.pdf)

Lab Sump Piping Failure Investigation Report Attachments, dated
July 21, 2010 (CO-092-10 Attachments.pdf)

Sump Investigation Report and Investigation Closure Request, dated
December 8, 2010 (CO-174-10 Sump Report.pdf)

Please let me know if you have any questions.

Thanks,
Liz

PLEASE NOTE:

New Street Address and Phone Number Below

Elizabeth Page, P.G.
Reiss Remediation, LLC
602 Strada Circle, Suite 121
Mansfield, TX 76063
Direct: (817) 842-9070
Fax: (817) 842-9110
Cell: (817) 723-4616

[attachment "CO-092-10.pdf" deleted by Brandon Perkins/R10/USEPA/US] [attachment "CO-092-10 Attachments.pdf" deleted by Brandon Perkins/R10/USEPA/US] [attachment "CO-174-10_Sump Report.pdf" deleted by Brandon Perkins/R10/USEPA/US]